

## Technical Comments

San Jacinto 2013 Ground Water Field Sampling Report (dated Jan. 2014)

EFB 01/21/13

Page 1 Introduction says results will be incorporated into RI, but the RI was finalized months ago.

Page 3 Aquifer testing is stated but the types of test were not stated (determination of S, T, yield)?

Page 4 Only two shallow wells were developed, yet a minimum of 3 is required for flow direction.

App A Cores were inconsistent with each other above the Beaumont clay layer, especially the first and last presented (at 20 foot depth) – so is the site heterogeneous subsurface?

Well Construction Details of first well presented regarding thickness of several horizons stated as 0 ft.